

Message (Digitally Signed)

---

**From:** Richardson, Trevor J CIV PSNS&IMF, Code 106.31 [trevor.richardson@navy.mil]  
**Sent:** 12/6/2018 10:38:37 PM  
**To:** Grandinetti, Robert [/o=ExchangeLabs/ou=Exchange Administrative Group (FYDIBOHF23SPDLT)/cn=Recipients/cn=9c73f8984588411fa3df484d6386a013-Grandinetti, Robert]  
**Subject:** PSNS & IMF Compliance Inspection Follow-up Information  
**Attachments:** Final Non\_Drydock Stormwater\_Phase I through III\_2010-13.pdf; CONTECH 2 Cartridge CatchBasin StormFilter.pdf; smime.p7s  
  
**Flag:** Follow up

Rob,

The 2010-2013 Non-Dry Dock Stormwater Study you requested is attached.

Links to the CONTECH website for more information on our stormwater filters:

Steel Yard (sheet steel storage area)

- CONTECH Vortechs <https://www.conteches.com/stormwater-management/treatment/vortechs>

Dry Dock 3 Outdoor Cutting Area

- CONTECH 2 Cartridge CatchBasin StormFilter (drawing attached)
- Information on the CONTECH StormFilter <https://www.conteches.com/stormwater-management/treatment/stormwater-management-stormfilter>

Recycled Metal Transfer Station and Pier B

- CONTECH CDS <https://www.conteches.com/stormwater-management/treatment/cds>
- Followed by CONTECH StormFilter Vault <https://www.conteches.com/stormwater-management/treatment/stormwater-management-stormfilter>

An electronic copy of the PSNS & IMF SWPPP and a blank stormwater inspection form are both in routing for public release, I will keep you updated on their progress.

If you have any more questions or would like any more information please let me know,

Trevor Richardson  
PSNS & IMF Code 106.32  
NPDES Program Manager  
☎: (360)476-0118  
📠: (360)535-2898